

Mercedes-Benz Australia/Pacific Pty Ltd
TAKATA Recall and Replacement Timetable

Vehicle		Recall Initiation and Replacement				Airbag Inflator Family
Designation	Model	Model Year	Initiation Release Date	Geographic Location	Date which Inflators are to be replaced	Inflator Type
164	ML-Class	2009 - 2011	May 2018	Nationwide	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver side inflator
164	GL-Class	2009 - 2012	May 2018	Nationwide		Driver side inflator
171	SLK-Class	2007 - 2008	May 2018	Nationwide		Driver side inflator
251	R-Class	2009 - 2013	May 2018	Nationwide		Driver side inflator
204	C-Class	2008 - 2009	June 2018	QLD, NT, WA	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver & passenger side inflator
204	C-Class	2010 - 2011	July 2018	QLD, NT, WA		Driver & passenger side inflator
204	C-Class	2012	August 2018	QLD, NT, WA	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Passenger side inflator
204	C-Class	2013	September 2018	QLD, NT, WA		Passenger side inflator
204	C-Class	2014 - 2015	October 2018	QLD, NT, WA	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Passenger side inflator
207	E-Class Cabrio	2010 - 2011	November 2018	QLD, NT, WA		Driver & passenger side inflator
207	E-Class Coupé	2010 - 2011	November 2018	QLD, NT, WA	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver & passenger side inflator
212	E-Class	2010 - 2011	November 2018	Nationwide		Driver & passenger side inflator
207	E-Class Cabrio	2012 - 2017	November 2018	QLD, NT, WA	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Passenger side inflator
207	E-Class Coupé	2012 - 2017	November 2018	QLD, NT, WA		Passenger side inflator
169	A-Class	2005 - 2010	February 2019	Nationwide	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver side inflator
197	SLS-Class Coupé	2011 - 2014	April 2019	Nationwide		Driver side inflator
197	SLS-Class Roadster	2012 - 2014	April 2019	Nationwide	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver side inflator
197	SLS-Class Coupé	2011 - 2014	17 July 2019	Nationwide		Passenger side inflator
197	SLS-Class Roadster	2012 - 2014	17 July 2019	Nationwide	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Passenger side inflator
204	C-Class	2008	January 2020	NSW & ACT		Driver & passenger side inflator
204	C-Class	2008	February 2020	VIC, SA, TAS	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver & passenger side inflator
204	C-Class	2009	March 2018	NSW, ACT, VIC, SA, & TAS		Driver & passenger side inflator
204	C-Class	2010 - 2011	April 2018	NSW, ACT, VIC, SA, & TAS	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver & passenger side inflator
204	C-Class	2012	April 2018	NSW & ACT		Passenger side inflator
204	C-Class	2012	May 2018	VIC, SA, TAS	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Passenger side inflator
204	C-Class	2013	May 2018	NSW, ACT, VIC, SA, & TAS		Passenger side inflator
204	C-Class	2014 - 2015	June 2018	NSW, ACT, VIC, SA, & TAS	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Passenger side inflator
207	E-Class Cabrio	2010	March 2020	NSW, ACT, VIC, SA, & TAS		Driver & passenger side inflator
207	E-Class Coupé	2010	March 2020	NSW, ACT, VIC, SA, & TAS	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver & passenger side inflator
207	E-Class Cabrio	2011	April 2020	NSW, ACT, VIC, SA, & TAS		Driver & passenger side inflator
207	E-Class Coupé	2011	April 2020	NSW, ACT, VIC, SA, & TAS	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver & passenger side inflator
207	E-Class Cabrio	2012 - 2014	May 2020	NSW, ACT, VIC, SA, & TAS		Passenger side inflator
207	E-Class Coupé	2012 - 2014	May 2020	NSW, ACT, VIC, SA, & TAS	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Passenger side inflator
207	E-Class Cabrio	2015 - 2017	June 2020	NSW, ACT, VIC, SA, & TAS		Passenger side inflator
207	E-Class Coupé	2015 - 2017	June 2020	NSW, ACT, VIC, SA, & TAS	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Passenger side inflator
461	G300 CDI Professional	2015 - 2018	February 2020	Nationwide		Driver side inflator

Mercedes-Benz Vans Australia Pacific Pty Ltd
TAKATA Recall and Replacement Timetable

Vehicle			Recall Initiation and Replacement			Airbag Inflator Family
Designation	Model	Model Year	Initiation Release Date	Geographic Location	Date which Inflators are to be replaced	Inflator Type
639	Viano, Vito, & Valente	2006–2012	31 July 2018	Qld, NT, WA	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver side inflator (with multifunction steering wheel)
	Viano, Vito, & Valente	2006–2008		NSW, ACT, Vic, SA, Tas		Driver side inflator (with multifunction steering wheel)
639	Viano, Vito, & Valente	2006 - 2014	30 August 2018	30 August 2018	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver side inflator (without multifunction steering wheel)
639	Viano, Vito, & Valente	2009–2010	31 July 2018	NSW, ACT, Vic, SA, Tas	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver side inflator (with multifunction steering wheel)
	Viano, Vito, & Valente	2011–2012		NSW, ACT, Vic, SA, Tas		Driver side inflator (with multifunction steering wheel)
639	Viano, Vito, & Valente	2009 - 2011	31 October 2018	Qld, NT, WA	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver side inflator (without multifunction steering wheel)
906	Sprinter ES Edition	2006- 2017	15 November 2018	Nationwide	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver & Passenger side inflator
	Sprinter ES Edition	2006- 2017		Nationwide		Driver side inflator
906	Sprinter	2006 – 2008	30 January 2019	Qld, NT, WA	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver & Passenger side inflator
	Sprinter	2006 – 2008		NSW, ACT, Vic, SA, Tas		Driver & Passenger side inflator
	Sprinter	2006 – 2008		Nationwide		Driver side inflator
639	Viano, Vito, & Valente	2006–2007	30 March 2019	NSW, ACT, Vic, SA, Tas	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver side inflator (without multifunction steering wheel)
906	Sprinter	2009 – 2011		Qld, NT, WA		Driver & Passenger side inflator
	Sprinter	2009 – 2012		Nationwide		Driver side inflator
906	Sprinter	2012 – 2014	30 April 2018	Qld, NT, WA	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver & Passenger side inflator
906	Sprinter	2009 – 2011	30 May 2019	2009 – 2011	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver and Passenger side inflators
	Sprinter	2013 – 2017		2013 – 2017		Driver side inflators
906	Viano, Vito, & Valente	2013–2014	30 June 2019	Nationwide	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver side inflator (with multifunction steering wheel)
	Viano, Vito, & Valente	2008–2012		NSW, ACT, Vic, SA, Tas		Driver side inflator (without multifunction steering wheel)
	Sprinter	2012 – 2014		NSW, ACT, Vic, SA, Tas		Driver and Passenger side inflators
	Sprinter	2015 – 2017		Nationwide		Driver and Passenger side inflators