

Mercedes-Benz Australia/Pacific Pty Ltd
TAKATA Recall and Replacement Timetable

Vehicle			Recall Initiation and Replacement		Airbag Inflator Family
Designation	Model	Model Year	Initiation Release Date	Date which Inflators are to be replaced	Inflator Type
164	ML-Class	2009 - 2011	May 2018	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver side inflator
164	GL-Class	2009 - 2012	May 2018		Driver side inflator
171	SLK-Class	2007 - 2008	May 2018		Driver side inflator
251	R-Class	2009 - 2013	May 2018		Driver side inflator
204	C-Class	2008 - 2009	June 2018	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver & passenger side inflator
204	C-Class	2010 - 2011	July 2018	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver & passenger side inflator
204	C-Class	2012	August 2018	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Passenger side inflator
204	C-Class	2013	September 2018	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Passenger side inflator
204	C-Class	2014 - 2015	October 2018	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Passenger side inflator
207	E-Class Cabrio	2010 - 2017	November 2018	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver side inflator
207	E-Class Coupé	2010 - 2017	November 2018		Driver & passenger side inflator
212	E-Class	2010 - 2011	November 2018		Driver & passenger side inflator
169	A-Class	2005 - 2010	December 2018	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver side inflator
197	SLS-Class Coupé	2011 - 2014	December 2018		Driver & passenger side inflator
197	SLS-Class Roadster	2012 - 2014	December 2018		Driver & passenger side inflator

Mercedes-Benz Vans Australia Pacific Pty Ltd
TAKATA Recall and Replacement Timetable

Vehicle			Recall Initiation and Replacement		Airbag Inflator Family
Designation	Model	Model Year	Initiation Release Date	Date which Inflators are to be replaced	Inflator Type
639	Viano, Vito, & Valente	2006 - 2014	31 July 2018	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver side inflator (with multifunction steering wheel)
639	Viano, Vito, & Valente	2006 - 2014	30 August 2018	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver side inflator (without multifunction steering wheel)
906	Sprinter ES Edition	2006- 2017	15 November 2018	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver & Passenger side inflator
906	Sprinter ES Edition	2006- 2017	15 November 2018		Driver side inflator
906	Sprinter	2006 - 2017	30 January 2019	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver & Passenger side inflator
906	Sprinter	2006 - 2017	30 January 2019		Driver side inflator