

Mercedes-Benz Australia/Pacific Pty Ltd
TAKATA Recall and Replacement Timetable

Vehicle			Recall Initiation and Replacement		Airbag Inflator Family
Designation	Model	Model Year	Initiation Release Date	Date which Inflators are to be replaced	Inflator Type
164	ML-Class	2009 - 2011	May 2018	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver side inflator
164	GL-Class	2009 - 2012	May 2018		Driver side inflator
171	SLK-Class	2007 - 2008	May 2018		Driver side inflator
251	R-Class	2009 - 2013	May 2018		Driver side inflator
204	C-Class	2008 - 2009	June 2018	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver & passenger side inflator
204	C-Class	2010 - 2011	July 2018	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver & passenger side inflator
204	C-Class	2012	August 2018	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Passenger side inflator
204	C-Class	2013	September 2018	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Passenger side inflator
204	C-Class	2014 - 2015	October 2018	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Passenger side inflator
207	E-Class Cabrio	2010 - 2011	November 2018	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver & passenger side inflator
207	E-Class Cabrio	2012 - 2017	November 2018		Passenger side inflator
207	E-Class Coupé	2010 - 2011	November 2018		Driver & passenger side inflator
207	E-Class Coupé	2012 - 2017	November 2018		Passenger side inflator
212	E-Class	2010 - 2011	November 2018		Driver side inflator
169	A-Class	2005 - 2010	February 2019	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018	Driver side inflator
197	SLS-Class Coupé	2011 - 2014	April 2019		Driver & passenger side inflator
197	SLS-Class Roadster	2012 - 2014	April 2019		Driver & passenger side inflator

Mercedes-Benz Vans Australia Pacific Pty Ltd
TAKATA Recall Initiation Schedule

Recall Initiation Date	Vehicle			Geographic Application, if applicable	Other factors, if applicable
	Designation	Model	Model Year		
31 July 2018	639	Viano, Vito, & Valente	2006–2012	Qld, NT, WA	Driver side inflator (with multifunction steering wheel)
	639	Viano, Vito, & Valente	2006–2008	NSW, ACT, Vic, SA, Tas	Driver side inflator (with multifunction steering wheel)
30 August 2018	639	Viano, Vito, & Valente	2006–2008	Qld, NT, WA	Driver side inflator (without multifunction steering wheel)
30 September 2018	639	Viano, Vito, & Valente	2009–2010	NSW, ACT, Vic, SA, Tas	Driver side inflator (with multifunction steering wheel)
	639	Viano, Vito, & Valente	2011–2012	NSW, ACT, Vic, SA, Tas	Driver side inflator (with multifunction steering wheel)
31 October 2018	639	Viano, Vito, & Valente	2009–2011	Qld, NT, WA	Driver side inflator (without multifunction steering wheel)
15 November 2018	906	Sprinter ES Edition	2006 – 2017	Nationwide	Driver and Passenger side inflators
	906	Sprinter ES Edition	2006 – 2017	Nationwide	Driver side inflators
30 January 2019	906	Sprinter	2006 – 2008	Qld, NT, WA	Driver and Passenger side inflators
	906	Sprinter	2006 – 2008	NSW, ACT, Vic, SA, Tas	Driver and Passenger side inflators
	906	Sprinter	2006 – 2008	Nationwide	Driver side inflator
30 March 2019	639	Viano, Vito, & Valente	2006–2007	NSW, ACT, Vic, SA, Tas	Driver side inflator (without multifunction steering wheel)
	906	Sprinter	2009 – 2011	Qld, NT, WA	Driver and Passenger side inflators
	906	Sprinter	2009 – 2012	Nationwide	Driver side inflators
30 April 2019	906	Sprinter	2012 – 2014	Qld, NT, WA	Driver and Passenger side inflators
30 May 2019	906	Sprinter	2009 – 2011	NSW, ACT, Vic, SA, Tas	Driver and Passenger side inflators
	906	Sprinter	2013 – 2017	Nationwide	Driver side inflators
30 June 2019	639	Viano, Vito, & Valente	2013–2014	Nationwide	Driver side inflator (with multifunction steering wheel)
	639	Viano, Vito, & Valente	2008–2012	NSW, ACT, Vic, SA, Tas	Driver side inflator (without multifunction steering wheel)
	906	Sprinter	2012 – 2014	NSW, ACT, Vic, SA, Tas	Driver and Passenger side inflators
	906	Sprinter	2015 – 2017	Nationwide	Driver and Passenger side inflators